

CHRYSLER STRUT TOWER CAPS

New to the Aftermarket

65% OE Failure Rate

- Comes Complete with Mounting Hardware
- Movement Code: B



Rusts Quickly-
A Must Stock Item in
Cold Areas of The Country

OE Part Fails Due to Rust and Corrosion



Part is a Reinforcement to the Shock

2 SKUs Cover Over 2 Million Registered Chrysler Minivans

MAKE/MODEL	YEARS	DESCRIPTION	PART NAME	DORMAN#
CHRYSLER				
GRAND VOYAGER	2000	LH	Strut Tower Repair Cap	924-206
GRAND VOYAGER	2000	RH	Strut Tower Repair Cap	924-207
TOWN & COUNTRY VAN	2000-96	LH	Strut Tower Repair Cap	924-206
TOWN & COUNTRY VAN	2000-96	RH	Strut Tower Repair Cap	924-207
DODGE				
CARAVAN, GRAND CARAVAN	2000-96	LH	Strut Tower Repair Cap	924-206
CARAVAN, GRAND CARAVAN	2000-96	RH	Strut Tower Repair Cap	924-207
PLYMOUTH				
VOYAGER, GRAND VOYAGER	2000-96	LH	Strut Tower Repair Cap	924-206
VOYAGER, GRAND VOYAGER	2000-96	RH	Strut Tower Repair Cap	924-207



Dorman Products, Inc.
P.O. Box 1800
Colmar, PA 18915
Corporate Office and
Customer Service
Service: 1-800-523-2492

2800115

©2008 Dorman Products, Inc.
No reproduction in
whole or in part without
prior written approval.

BE THE FIRST TO KNOW!



**Sign Up for
Product
Update Emails**

Go to www.DormanProducts.com and Click on the Link
Above to Sign Up for New Product Information Alerts!

New Product Idea Hotline 1-800-336-3575
www.DormanProducts.com

NEW PRODUCTS • NEW SOLUTIONS • NEW OPPORTUNITIES